
Intelligent FOL Support Statement

This document details the support status of the various EOD/PPM Intelligent fibre optic links.

No Longer Supported

The following products are **no longer supported**. Repairs will not be undertaken on these products due to component obsolescence. We recommend examining the [replacement systems](#).

- Sentinel 1000
- Sentry 1000
- Sentry 150
- Sigma 25
- Sigma 5
- Sprint
- Sprite
- FOL1000
- FOL1000S
- FOL500
- FOL150
- FOLNET Controllers
- FOLNET Racks
- Sentinel II RX module
- Sentry II RX module

The support policies outlined below are MINIMUM time frames based on the current availability of components.

Supported until 1st January 2012

- Sentinel II TX
- Sentry II TX
- System Controller (compatible replacement due before 2012, LXI support)

Supported until 1st January 2018

- Sentinel IIsc TX and RX modules
- Sentry IIsc TX and RX modules

Compatibility Notes

FOLNET mainframes and controllers are not compatible with the Sentinel IIsc or Sentry IIsc systems.